



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ:2

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ, ਬਠਿੰਡਾ।

ਫੋਨ ਅਤੇ ਫੈਕਸ: 0164-2212428

email: - xenc2bti@gmail.com

ਮੀਮੋ ਨੰ: 315

ਮਿਤੀ: 24/04/2023

ਵੱਲ,

Delhi Public School,
Bathinda.

ਵਿਸ਼ਾ:- ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ ਸਾਲ (2023-2024)

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਵਿਸ਼ੇ ਅੰਕਿਤ ਬਿਲਡਿੰਗ ਦਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਭਤੇਮ ਸ਼ਾਖਾ, ਗੋਨਿਆਣਾ ਐਟ ਬਠਿੰਡਾ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ। ਮੌਕੇ ਤੇ ਦੇਖਣ ਤੇ ਬਿਲਡਿੰਗ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਉਹਨਾਂ ਦੀ ਰਿਪੋਰਟ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਸਾਲ 2023-24 ਅਪਟੂ 31.03.2024 ਤੱਕ ਦਾ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਇਸ ਸ਼ਰਤ ਤੇ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਕਿ ਉਕਤ ਬਿਲਡਿੰਗ ਦਾ ਫਾਇਰ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 20.03.2024 ਤੱਕ ਖਤਮ ਹੋਣ ਉਪਰੰਤ ਸਕੂਲ ਫਾਇਰ ਸਰਟੀਫਿਕੇਟ ਆਪਣੇ ਪੱਧਰ ਤੇ ਦੁਬਾਰਾ ਲੈਣਾ ਯਕੀਨੀ ਬਣਾਏਗਾ, ਪੰਜਾਬ ਸਰਕਾਰ ਵੱਲੋਂ ਰੋਡ ਅਸੈਸ ਜਾਂ ਕੋਈ ਫੀਸ ਭਰਨ ਸਬੰਧੀ ਜਾਰੀ ਕੀਤੀਆਂ ਗਈਆਂ ਹਦਾਇਤਾਂ ਲਈ ਇੰਨ-ਬਿੰਨ ਪਾਬੰਧ ਹੋਵੇਗੇ।


ਨੱਥੀ/ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ
ਨਕਸ਼ਾ।


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 2 ਭਤੇਮ ਸ਼ਾਖਾ,
ਬਠਿੰਡਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਮਿਤੀ:.....

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਭਤੇਮ ਸ਼ਾਖਾ, ਗੋਨਿਆਣਾ ਐਟ ਬਠਿੰਡਾ ਨੂੰ ਉਹਨਾਂ ਦੇ ਦਫਤਰ ਦੇ ਪੱਤਰ ਨੰ: 31 ਮਿਤੀ 20.04.2023 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 2 ਭਤੇਮ ਸ਼ਾਖਾ,
ਬਠਿੰਡਾ।

PERFORMA FOR THE SAFETY OF THE SCHOOL BUILDING

1. Name of the School/Institution : **DELHI PUBLIC SCHOOL**
2. Location : **BHOKRA (Bathinda)**
3. Plot Area : **106 KANAL 16 $\frac{1}{3}$ MARLA**
4. Plinth Area : **12937 Sq. Mtr 1,39,752 Sq. Ft**
5. No. Of Storeys : **3**
6. Year of Construction of Building : **2003**
7. **Whether the building has been constructed under the supervision of the qualified Engineer, If so**
 - a) Name of the Engineer With qualification : **M/S BUILD WELL GROUP**
 - b) Address of the Engineer **KAMLA NEHRU COLONY
BATHINDA**
 - c) Set of Structural drawings used in the Construction
8. **Whether the building has constructed for the purpose of**
 - a) School/College (Yes/No)
 - b) Residential purpose & converted for the use of school (Yes/No)
 - c) Converted for School (Yes/No)
9. **Material used for roofs: -**
 - a) R.C.C. Slabs (Yes/No)
 - b) R.C. Joints & Battens (Yes/No)
 - c) Wooden joints & Battens (Yes/No)
 - d) Arch (Bricks) (Yes/No)
10. **Material used for walls**
 - a) Mud Mortar (Yes/No)
 - b) Cement Mortar (Yes/No)
 - c) Plaster (i) Line Mortar (ii) Cement Mortar (Yes/No)
11. **Flooring:**
 - a) Conglomerate Kota Stone (Yes/No)
 - b) Tarrazo (Yes/No)
 - c) Brick Paving (Yes/No)
12. **A detailed drawing indicating dimensions of the rooms
Alongwith the size and location of doors & windows is attached:** **Yes**

13. General

i) In case of double story Building 1.5 meter
Width upstairs are constructed or Not

(Yes/No)

II) Whether all class room are provided two door


(Yes/No)

III) Whether fire safety measures have been adopted and are in
Working condition

(Yes/No)

Dated :

Signature of Principal



(For the use of the PWD, B & R Department)

a) I Harinder Singh S.D.E. along with Anil Garg
have visited above mentioned school on 20-04-2023
and have visuable inspect from all angles of safety and find it fit for normal use as
school building.

b) In case any addition/alteration of exemption and the same be carried out under the
supervision of a technically qualified Engineer and this certificate may again be
obtained after the completion from the undersigned.

c) In case the building is affected by flood or there is settlement of walls/foundation
of sagging of roofs etc. Immidiate inspection of the undersigned by arranged to
check the stability and the safety of the building.

d) The building can be safely occupied for normal use upto 31-03-2024

(Indicate year upto which it can be used)

e) Inspection fee has been deposited by the school vide G.R. No. 971690

dt. 19/04/23 amounting to Rs. 20,000/-

Countersigned

Executive Engineer,

Sub Divisional Engineer
Sub Divisional Engineer
Const. Sub Divn. PWD B&R
Goniana at Bathinda